



1/20

[FIG. 1]




2/20


[FIG. 2]



[FIG. 3]




[FIG. 4]




3/20

[FIG. 5]




4/20

[FIG. 6]




5/20

[FIG. 7]




6/20

[FIG. 8]




7/20

[FIG. 9]




8/20

[FIG. 10]




9/20

[FIG. 11]




10/20

[FIG. 12]




11/20

[FIG. 13]



12/20

[FIG. 14]







[FIG. 15]

142A

Defect address	Spare address	Other information
Address aaaa	Address gggg	
Address bbbb	Address kkkk	
Address cccc	Address mmmm	
Address dddd	Address nnnn	
⋮	⋮	


13/20

[FIG. 16]




14/20

[FIG. 17]




15/20

[FIG. 18]




16/20

[FIG. 19]




17/20

[FIG. 20]




18/20

[FIG. 21]




19/20

[FIG. 22]



20/20

[FIG. 23]



[FIG. 24]

